

FIG. 1




FIG. 3




FIG. 2




Fig. 4




Fig. 5




Fig. 6




Fig. 9











Fig. 7

Fig. 8







170




FIG. 20

FIG. 18





FIG. 19




FIG. 21




FIG. 22A




FIG. 22B

10007061 419074




FIG. 23

FIG. 24A




FIG. 24B




FIG. 24C





FIG. 24D









Fig. 26

Fig. 25




FIG. 29




FIG. 30




FIG 31




FIG. 32










FIG. 33



10007051 43001
FOOT " 5000001

Pressure



Time

FIG. 39

Pressure

Pressure





Fig. 40

Time

10007061 T902000F

Pressure



Time

FIG. 41

10007051 443004

Pressure






Fig. 42

Time

Pressure
FOOT
1000
700
500
300
100



FOOT
Pressure




Time

FIG. 44

FOOT T 902000

Pressure



Time

FIG. 45

Pressure




FIG 46

Pressure





FIG. 47

Time

10007051-113001

Pressure



Time

FIG. 48

10007001 113001
Pressure




FIG. 49

Time

10007061-43004

Pressure




FIG. 5D

Time

1000000
Pressure




FIG. 51

Time

10007061-13001

Pressure




FIG. 52

Time

10007061-13007

Pressure




FIG 53

Time

Pressure




FIG. 54

Time